

Super Conductor Materials, Inc.

391 Spook Rock Industrial Park, Suffern, NY 10901 · 845.368.0240 · Fax 845.368.0250 · www.scm-inc.com

Chemtrec: (800) 424-9300 Poison Center: (800) 562-8236 Revision Date: January 8th, 2019

SAFETY DATA SHEET

Identity: Silicon Monoxide

Formula: SiO

SECTION I - GENERAL INFORMATION

Manufacturer: Super Conductor Materials, Inc.

The information below is believed to be accurate and represents the best information available to Super Conductor Materials, Inc. However, SCM makes no warranty, expressed or implied with respect to such information and assumes no liability resulting from its use.

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

Molecular weight: 44.09

CAS #	OSHA PEL	ACGIH TLV	%
10097-28-6	N/A	N/A	0.0-100.0%

SECTION III – PHYSICAL/CHEMICAL CHARACTERISTICS

Physical States: Solid

Boiling Point: 1880.00°C Melting Point: >1702.00°C Evaporation Rate: N/A Solubility in water: Insoluble Vapor Pressure (vs. air or mmHg): Density: 2.13 g/cm³ Flash Point: N/A

Appearance and odor: Black powder and pieces, no odor.

SECTION IV - FIRE AND EXPLOSION HAZARD DATA:			
Method Used: Unknown	Explosive Limits: LEL: N/A	UEL: N/A	

Extinguishing Media: Use suitable extinguishing agent for surrounding material and type of fire

Special Fire Fighting Procedures:

Firefighters must wear full face, self-contained breathing apparatus with full protective clothing to prevent contact with skin and eyes. Fumes from fire are hazardous. Isolate runoff to prevent environmental pollution.

Unusual Fire and Explosive Hazards:

-Silicon monoxide may emit toxic fumes if involved in a fire.

-May be flammable and possibly pyrophoric on contact with air at extremely elevated temperatures.



Super Conductor Materials, Inc.

391 Spook Rock Industrial Park, Suffern, NY 10901 · 845.368.0240 · Fax 845.368.0250 · www.scm-inc.com

SECTION V - REACTIVITY DATA

Stability: Stable Conditions to Avoid (instability): None Incompatibility: Strong acids and bases

Hazardous Decomposition or Byproducts: Silicon dioxide *Hazardous Polymerization:* Will not occur *Conditions to avoid (hazardous polymerization):* None

SECTION VI - HEALTH HAZARD DATA

<u>Route of Entry</u>: Inhalation? Yes Skin? No Eyes? No Ingestion? No Other: No

MAY CAUSE IRRITATION TO THE RESPIRATORY SYSTEM

Signs and Symptoms of Overexposure:

Inhalation: Coughing, shortness of breath, wheezing, change in breathing capacity and cyanosis. *Ingestion:* No acute or chronic health effects recorded. *Skin:* May cause redness. *Eye:* May cause redness, itching and watering.

Health Hazards (Acute and Chronic):

Inhalation: Acute: May cause irritation to the respiratory system. Chronic: May cause pneumoconiosis, pulmonary fibrosis and silicosis.

Ingestion: Acute: No acute health effects recorded. Chronic: No chronic health effects recorded.

Skin: Acute: May cause abrasive irritation. Chronic: No chronic health effects recorded.

Eye:

Acute: May cause abrasive irritation. Chronic: No chronic health effects recorded.

Target Organs: May affect the respiratory system.Carcinogenicity:NTP? NoIARC Monographs?NoOSHA Regulated? NoMedical Conditions Aggravated by Exposure:Pre-existing respiratory, gastric and skin disorders.



Super Conductor Materials, Inc.

391 Spook Rock Industrial Park, Suffern, NY 10901 · 845.368.0240 · Fax 845.368.0250 · www.scm-inc.com

Emergency and First Aid Procedures:

Inhalation: Remove victim to fresh air, keep warm and quiet, and give oxygen if breathing is difficult; seek medical attention

Ingestion: Give 1-2 glasses of milk or water and induce vomiting, seek medical attention. Never induce vomiting or give anything by mouth to an unconscious person

Skin: Remove contaminated clothing, brush material off skin, wash affected area with mild soap and water, and seek medical attention if symptoms persist

Eye: Flush eyes with lukewarm water, lifting upper and lower eyelids for at least 15 minutes and seek medical attention

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be taken in case material is released or spilled:

Wear appropriate respiratory and protective equipment specified in section VIII. Isolate spill area, provide ventilation and extinguish sources of ignition. Vacuum up spill using a high efficiency particulate absolute (HEPA) air filter and place in a closed container for proper disposal. Take care not to raise dust.

Waste disposal method:

Dispose of in accordance with state, local, and federal regulations.

Hazard Label Information:

Store in cool, dry area and in tightly sealed container. Wash thoroughly after handling.

SECTION VIII - CONTROL MEASURES

Protective Equipment Summary (Hazard Label Information):

NIOSH approved respirator, impervious gloves, safety glasses, clothes to prevent contact.

Ventilation:

Local Exhaust: To maintain concentration at low exposure levels. Mechanical (General): Recommended.

Work/Hygienic/Maintenance Practices:

Implement engineering and work practice controls to reduce and maintain concentration of exposure at low levels. Use good housekeeping and sanitation practices. Do not use tobacco or food in work area. Wash thoroughly before eating or smoking. Do not blow dust off clothing or skin with compressed air.

Please be advised that N/A can either mean Not Applicable or No Data Has Been Established