

Super Conductor Materials. Inc.

391 Spook Rock Industrial Park, Suffern, NY 10901 · 845.368.0240 · Fax 845.368.0250 · www.scm-inc.com

Chemtrec: (800) 424-9300 Poison Center: (800) 562-8236 Revision Date: January 8th, 2019

SAFETY DATA SHEET

Identity: Titanium Aluminide

Formula: Ti3Al

SECTION I - GENERAL INFORMATION

Manufacturer: Super Conductor Materials, Inc.

The information below is believed to be accurate and represents the best information available to Super Conductor Materials, Inc. However, SCM makes no warranty, expressed or implied with respect to such information and assumes no liability resulting from its use.

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

Molecular Weight: 170.68

CAS #	OSHA PEL	ACGIH TLV	%
39410-63-4	15 mg/m3	10 mg/m3	0.0-100.0%

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

Physical States: Solid

Boiling Point: Melting Point: Evaporation Rate (butyl acetate=1): Solubility in water: Vapor Pressure: Specific Gravity: (water=1): Flash Point:

Appearance and odor: Pieces, no odor

SECTION IV - FIRE AND EXPLOSION HAZARD DATA:

Method Used: UnknownExplosive Limits:LEL:NEUEL:NEExtinguishing Media: Use suitable extinguishing agent for surrounding materials and type of fire.

Special Fire Fighting Procedures: Firefighters must wear full face, self-contained breathing apparatus with full protective clothing to prevent contact with skin and eyes. Fumes from fire are hazardous. Isolate runoff to prevent environmental pollution.

Unusual Fire and Explosion Hazards: None recorded

SECTION V - REACTIVITY DATA

Stability: Stable Conditions to Avoid (stability): None



Super Conductor Materials, Inc.

391 Spook Rock Industrial Park, Suffern, NY 10901 · 845.368.0240 · Fax 845.368.0250 · www.scm-inc.com

Incompatibility (Materials to Avoid): None recorded

Hazardous Decomposition or Byproducts: None recorded *Hazardous Polymerization*: Will not occur *Conditions to Avoid (Hazardous Polymerization):* None

SECTION VI - HEALTH HAZARD DATA					
<u>Route of Entry</u> : Inhalation? Yes	Ingestion? Yes	Skin? Yes	Eyes? Yes	Other? No	

To the best of our knowledge the chemical, physical and toxicological properties of titanium aluminide have not been thoroughly investigated and recorded.

TITANIUM: This material is generally considered to be physiologically inert. There are no reported cases in the literature where titanium as such has caused human intoxication. The dusts of titanium or most titanium compounds such as titanium oxide may be placed in the nuisance category. (Sax, Dangerous Properties of Industrial Materials, eighth edition)

ALUMINUM: Aluminum compounds have many commercial uses and are commonly found in industry. Many of these materials are active chemically and thus exhibit dangerous toxic and reactive properties. Inhalation of fine aluminum oxide particles is associated with Shaver's disease. (Sax, Dangerous Properties of Industrial Materials, eighth edition)

Sign and Symptoms of Overexposure:

Inhalation: May cause redness, dry, sore nose and throat, coughing and shortness of breath. *Ingestion*: No acute and chronic health effects recorded. *Skin*: May cause redness, itching, and inflammation. *Eye*: May cause redness, itching, and inflammation and watering.

Health Hazards (Acute and Chronic):

Inhalation:

Acute: Inhalation of finely divided aluminum powder has been reported to cause pulmonary fibrosis. May cause irritation to the respiratory tract.

Chronic: May cause pulmonary fibrosis.

Ingestion:

Acute: No acute health effects recorded. Chronic: May be implicated in Alzheimer's disease.

Skin:

Acute: May cause abrasive irritation. Chronic: No chronic health effects recorded.

Eye: Acute: May cause abrasive irritation. Chronic: No chronic health effects recorded.

Target Organ: No target organs recordedCarcinogenicity:NTP? NoIARC Monographs? NoOSHA Regulated? NoMedical Conditions Aggravated by Exposure:Pre-existing respiratory disorder



Super Conductor Materials, Inc.

391 Spook Rock Industrial Park, Suffern, NY 10901 · 845.368.0240 · Fax 845.368.0250 · www.scm-inc.com

Emergency and First Aid Procedures:

Inhalation:	Remove victim to fresh air, keep warm and quiet, and give oxygen if breathing is
	difficult; seek medical attention
Ingestion:	1-2 glasses of milk or water and induce vomiting, seek medical attention. Never induce

- *Ingestion:* 1-2 glasses of milk or water and induce vomiting, seek medical attention. Never induce vomiting or give anything by mouth to an unconscious person.
- *Skin:* Remove contaminated clothing, brush material off skin, wash affected area with mild soap and water, and seek medical attention immediately.
- *Eye:* Flush eyes with lukewarm water, lifting upper and lower eyelids for at least 15 minutes and seek medical attention immediately.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be taken in case material is released or spilled:

Wear appropriate respiratory and protective equipment specified in section VIII-Control Measures. Isolate spill area, provide ventilation. Vacuum up spill using a high efficiency particulate absolute (HEPA) air filter and place in a closed container for proper disposal. Take care not to raise dust.

Waste disposal method:

Dispose of in accordance with state, local, and federal regulations.

Hazard Label Information:

Store in cool, dry area and in tightly sealed container. Wash thoroughly after handling.

SECTION VIII - CONTROL MEASURES

Protective Equipment Summary (Hazard Label Information):

NIOSH approved respirator, impervious gloves, safety glasses, clothes to prevent contact.

Ventilation:

Local Exhaust: To maintain concentration at low exposure levels. Mechanical (General): Good general ventilation is recommended.

Work/Hygienic/Maintenance Practices:

Implement engineering and work practice controls to reduce and maintain concentration of exposure at low levels. Use good housekeeping and sanitation practices. Do not use tobacco or food in work area. Wash thoroughly before eating or smoking. Do not blow dust off clothing or skin with compressed air.

Please be advised that N/A can either mean Not Applicable or No Data Has Been Established